



| | | | |
|---|-----------------|---|---|
|  | Form Title: | ENGINEERING BULLETIN | Document #: EB-03-20 <small>(Form: DEF-003A-1)</small> |
| | | | Revision: 0 |
| | Document Title: | Part Number Changes – Work Lamps | Date: July 10, 2020 |
| | | | Page: 1 of 2 |

Description of Bulletin: This bulletin is to alert of the change to part numbers for work lamps that reduce the quantity of part numbers and creates smart numbers.


Background Details: The original part numbers were made customer specific and that created multiple part numbers that were the same part. This caused confusion both internally and with customers. The new part numbers are created according to the legend shown below.

Bulletin Details: The new part numbers have not changed the form, fit or function of the parts.



| Old Part Number | New Number |
|-----------------|---------------|
| 315001 | 3G01-012-04 |
| 315003 | 3G01-012-04S |
| 315005 | 3G01-012-05 |
| 315007 | 3G01-012-05S |
| 315009 | 3G01-012-04E |
| 315010 | 3G01-012-04SE |
| 315011 | 3G01-012-05E |
| 315012 | 3G01-012-05SE |
| 315501 | 3G01-012-01 |
| 315503 | 3G01-012-01S |
| 315509 | 3G01-012-01E |
| 315510 | 3G01-012-01SE |
| 315511 | 3G01-012-03E |
| 315512 | 3G01-012-03SE |
| 315521 | 3G01-012-02 |
| 315523 | 3G01-012-02S |
| 315531 | 3G01-012-03 |
| 315533 | 3G01-012-03S |

| Old Part Number | New Number |
|-----------------|---------------|
| 325001 | 3G02-012-04 |
| 325003 | 3G02-012-04S |
| 325005 | 3G02-012-05 |
| 325007 | 3G02-012-05S |
| 325009 | 3G02-012-04E |
| 325010 | 3G02-012-04SE |
| 325011 | 3G02-012-05E |
| 325012 | 3G02-012-05SE |
| 325501 | 3G02-012-01 |
| 325503 | 3G02-012-01S |
| 325509 | 3G02-012-01E |
| 325510 | 3G02-012-01SE |
| 325511 | 3G02-012-03E |
| 325512 | 3G02-012-03SE |
| 325521 | 3G02-012-02 |
| 325523 | 3G02-012-02S |
| 325531 | 3G02-012-03 |
| 325533 | 3G02-012-03S |

| | | | | |
|---|-----------------|---|--------------------|----------------------|
|  | Form Title: | <p align="center">ENGINEERING BULLETIN</p> | Document #: | EB-03-20 |
| | | | (Form: DEF-003A-1) | Revision: |
| | Document Title: | <p align="center">Part Number Changes – Work Lamps</p> | Date: | July 10, 2020 |
| | | | Page: | 2 of 2 |

| Old Part Number | New Number | Old Part Number | New Number | Old Part Number | New Number |
|-----------------|---------------|-----------------|--------------|-----------------|----------------|
| M315-02-0728 | 3G01-012-06S | M325-02-0611 | 3G03-180-05S | M325-08-0335 | 3W05-006-03 |
| M315-02-1000 | 3G01-012-07S | M325-02-0623 | 3G03-360-01 | M325-09-0702 | 3G04-120-01 |
| M315-03-1000 | 3G01-012-08S | M325-02-0685 | 3G03-144-01S | M325-09-0922 | 3G03-120-04S |
| M315-06-1000 | 3W01-012-04SE | M325-02-0688 | 3G03-180-04S | M325-10-0017 | 3G04-360-01S |
| M315-09-1000 | 3B01-012-05S | M325-02-0858 | 3G04-180-01 | M325-10-0667 | 3G03-480-04S |
| M315-10-1000 | 3W01-012-04S | M325-02-0974 | 3G03-420-01S | M325-10-0922 | 3G08-168-04S |
| M315-13-1000 | 3W01-012-05S | M325-03-0341 | 3G05-006-01S | M325-11-0922 | 3G08-168-01S |
| M315-16-1000 | 3W01-012-01 | M325-03-0364 | 3G04-240-01S | M325-12-0017 | 3G04-360-01 |
| M315-18-1000 | 3B01-012-01 | M325-03-0404 | 3G04-360-01S | M325-12-1000 | 3W02-012-04SE |
| M315-19-1000 | 3W01-012-01S | M325-03-0590 | 3W03-360-03 | M325-13-0667 | 3G03-480-01S |
| M315-22-1000 | 3B01-012-01S | M325-03-0667 | 3G06-084-04 | M325-15-0667 | 3G07-162-01S04 |
| M315-23-1000 | 3W01-012-03 | M325-03-0702 | 3G03-120-04 | M325-15-1000 | 3B02-012-04S |
| M315-24-1000 | 3W01-012-03S | M325-03-0736 | 3G03-240-03 | M325-16-1000 | 3W02-012-05S |
| M315-25-1000 | 3W01-012-04 | M325-03-0842 | 3G03-180-04S | M325-17-1000 | 3W02-012-04S |
| M315-28-1000 | 3G01-180-01S | M325-03-0926 | 3G03-300-04S | M325-19-1000 | 3B02-012-05S |
| M325-01-0017 | 3G04-360-04S | M325-03-1000 | 3G02-012-07S | M325-21-0667 | 3G07-108-01S07 |
| M325-01-0130 | 3G07-132-04S | M325-04-0404 | 3G04-720-01S | M325-22-0667 | 3G07-108-01 |
| M325-01-0238 | 3G07-120-04SE | M325-04-0738 | 3G03-096-01 | M325-24-0667 | 3G07-108-01S06 |
| M325-01-0326 | 3G03-120-04S | M325-04-0842 | 3G03-300-04 | M325-25-1000 | 3B04-240-01S |
| M325-01-0364 | 3G04-240-04S | M325-04-0922 | 3G08-230-07S | M325-28-1000 | 3B02-012-05 |
| M325-01-0404 | 3G04-360-04SE | M325-04-0926 | 3G03-300-01S | M325-29-1000 | 3W02-012-05E |
| M325-01-0540 | 3G03-096-05SE | M325-04-0981 | 3G03-240-01 | M325-32-1000 | 3W02-012-01 |
| M325-01-0590 | 3W02-012-01S | M325-05-0017 | 3G04-360-05S | M325-33-0667 | 3G06-042-04S |
| M325-01-0611 | 3G03-024-05S | M325-05-0238 | 3G07-120-01S | M325-33-1000 | 3W02-012-01S |
| M325-01-0623 | 3G03-360-04S | M325-05-0478 | 3G03-144-01S | M325-34-0667 | 3G06-042-01S |
| M325-01-0634 | 3G05-006-01S | M325-05-0611 | 3G03-180-03S | M325-34-1000 | 3B02-012-01 |
| M325-01-0667 | 3G06-084-04S | M325-05-0738 | 3G03-144-01 | M325-35-1000 | 3B02-012-01S |
| M325-01-0688 | 3G03-180-04 | M325-06-0478 | 3G06-030-01S | M325-36-1000 | 3W05-006-03 |
| M325-01-0788 | 3G03-180-01S | M325-06-0702 | 3G03-360-04 | M325-37-1000 | 3W02-012-03 |
| M325-01-0853 | 3G03-120-04S | M325-06-0922 | 3G02-012-07S | M325-38-1000 | 3W02-012-03S |
| M325-01-0898 | 3G02-030-06 | M325-06-1000 | 3G05-006-04 | M325-39-1000 | 3B02-012-03 |
| M325-01-0953 | 3G04-456-04S | M325-07-0017 | 3G04-360-07S | M325-40-1000 | 3B02-012-03S |
| M325-01-0974 | 3G03-420-01 | M325-07-0326 | 3G03-120-01S | M325-42-1000 | 3B02-012-02S |
| M325-02-0042 | 3G06-018-01S | M325-07-0335 | 3G05-006-01 | M325-44-1000 | 3W02-012-02S |
| M325-02-0326 | 3G03-360-04S | M325-08-0017 | 3G04-360-08S | M325-47-1000 | 3W02-012-01SE |
| M325-02-0590 | 3W03-360-02 | M325-08-0326 | 3G06-024-03S | | |